








R100 Plus

1-Speed, 120 Volt, 1 Phase, 60Hz., 5/16 HP.

1725 RPM, 7 Amps



Click on Red Dot
OR
Call us
800-465-6060



ACCESSORIES

